

# A case study of Seismic Evaluation of Steel Buildings with rapid evaluation method

Alex Kurniawandy<sup>1</sup>, Shoji Nakazawa<sup>2</sup>

<sup>1</sup>Department of Civil Engineering, Universitas Riau, Pekanbaru, 28293 Indonesia

<sup>2</sup>Professor, Departement of Architecture and Civil Engineering, Toyohashi University of Technology  
1-1 Tempaku-cho, Toyohashi, 441-8580 Japan

\*\*\*

**Abstract** - This paper discusses the seismic evaluation of steel buildings with the rapid evaluation method. The recent earthquakes have exposed the vulnerability of the existing buildings in Indonesia. The need for evaluating the seismic adequacy of the existing structures has come into focus. To carry out a seismic evaluation, a simplified procedure for evaluation is highly in need. A rapid evaluation method has been conducted in this research refers to ASCE 41-13 Seismic Evaluation and Retrofit of Existing Building. There are three parts of the procedure has been done. A set of basic checklist considers to the geometry of the structure and a set structural checklist with focussing lateral force resisting element. Nonstructural checklist focus on finishing appliance, electrical, mechanical and plumbing system at the end of the part.

A case study building with steel moment frame structure conforms to common building type S1 in ASCE 41-13 benchmark. Structure model is steel special moment frame which consists of 6th stories. The structure is located in Padang city of Indonesia, which has a high level of seismicity and site class stiff soil. Seismic design category base on spectral design response is D category. The model was analyzed for gravity, and seismic load using Indonesian code refers to SNI 1727:2013 and SNI 1726:2012. The design generated according to specification for structural steel buildings in Indonesia refers to SNI 1729:2015.

Weak story and soft story able to detect rapidly in the basic checklist. Furthermore, it has deficiencies in the column flexural stress due to the strong column and weak beam not compliant in the structural checklist. Infill walls placed in moment frame designed not to resist seismic load subjected to damage due to no isolation. Detailing beam column joint and panel zone stiffness also needs to pay attention to the steel structure. The result of this rapid evaluation recommends that this building requires further evaluation.

**Key Words:** Seismic, Rapid Evaluation, Steel Structure, Deficiencies, Retrofit.

## 1. INTRODUCTION

Earthquakes are a disaster that can happen anytime and anywhere. Indonesia is a country that often experienced an earthquake. The cause of the territory of Indonesia located in three tectonic plates such as Eurasian, Pacific, and Indo-Australian. These boundaries will continue to move and collide each other which is the cause of the earthquake.

Furthermore, Indonesia lies in the Pacific ring of fire. A lot of active volcanos become the earthquake potential increased [1].

There are series of earthquake events that have occurred in Indonesia. The USGS information center, before 2004, the most recent megathrust earthquakes along the Sumatran-Andaman plate boundary were in 1797 (M 8.7-8.9), 1833 (M 8.9-9.1) and 1861 (M8.5). Since 2004, much of the Sunda megathrust between the northern Andaman Islands and Enggano Island, a distance of more than 2,000 km, has ruptured in a series of large subduction zone earthquakes - most rupturing the plate boundary south of Banda Aceh. The great M 9.1 earthquake of December 26, 2004, which produced a devastating tsunami, ruptured much of the boundary between Myanmar and Simeulue Island offshore Banda Aceh. Immediately to the south of the great 2004 earthquake, the M 8.6 Nias Island earthquake of March 28, 2005 ruptured a 400-km section between Simeulue and the Batu Islands. Farther south in the Mentawai islands, two earthquakes on September 12, 2007 of M 8.5 and M 7.9 occurred in the southern portion of the estimated 1797 and 1833 ruptures zone, which extends from approximately Enggano Island to the northern portion of Siberut Island. Smaller earthquakes have also been locally important: an M 7.6 rupture within the subducting plate caused considerable damage in Padang in 2009, and an M 7.8 rupture on October 25, 2010 occurred in the shallow portion of the megathrust to the west of the Mentawai Islands, and caused a substantial tsunami on the west coast of those islands. In addition to the current seismic hazards along this portion of the Sunda arc, this region is also recognized as having one of the highest volcanic hazards in the world. One of the most dramatic eruptions in human history was the Krakatau eruption on August 26-27, 1883, a volcano just to the southeast of the island of Sumatra, which resulted in over 35, 000 casualties [2].

It is difficult to estimate precisely how much an earthquake magnitude will occur during the life of the building. The building standards in Indonesia currently set SNI 1726: 2012 as a guide for estimating earthquake loads. For buildings which have built with earthquake loads not complied with this standard, it is necessary to re-evaluate. There are differences between rapid visual screening and rapid screening method. Rapid visual screening is based on visual investigation and only take a short time to investigate a structure. On the other hand, rapid evaluation is further

detail than rapid screening. It is recommended to conduct rapid visual screening before carried out the rapid evaluation method. This research explains an evaluation using the rapid evaluation method particularly for steel structural building.

## 2. STRUCTURAL EVALUATION

Structural evaluation of building due to the seismic load is carried out referring to the guidance of FEMA 310, 1998, then standardized on ASCE 31-03. Currently ASCE 31-03 "Seismic Evaluation of existing building" and ASCE 41-06 "Seismic rehabilitation of existing building" merging become ASCE 41-13. Like FEMA 310, ASCE 41-13 has a procedure for evaluating divided into three tiers. Tier 1 Screening phase as rapid evaluation, Tier 2 Deficiency based evaluation, utilizes more involved checks of the building to provide a deeper understanding of the building's design and Tier 3 Systematic evaluation procedure, provides a full building review including linear and non-linear performance-based analysis and design options. If the result of Tier 1 has some deficiencies, Tier 2 and Tier 3 evaluation provide more detailed and complex information. The screening purpose is to screen out if the building complies with criteria according to description parameters mentioned in this guidance. There are three parts of the rapid evaluation which covers building configuration, structural and nonstructural components. The aim of this research is simulating rapid evaluation of structure only [3, 4].

There are many types of building are classified as benchmark building as per AISC 41-13. Benchmark is related to material and system element as resisting seismic force such as wood structure, steel structure, reinforcement concrete, precast system and hybrid system. In this research, building type is classified in accordance with S1 benchmark building. It consists of a frame assembly of steel beams and steel columns. Floor and roof framing consists of cast-in-place concrete slabs or metal deck with concrete fill supported on steel beams, open web joists, or steel trusses. Seismic forces are resisted by steel moment frames that develop their stiffness through rigid or semi-rigid beam-column connections. Where all connections are moment-resisting connections, the entire frame participates in seismic force resistance. Where only selected connections are moment-resisting connections, resistance is provided along discrete frame lines. Columns are oriented so that each principal direction of the building has columns resisting forces in strong axis bending. Diaphragms consist of concrete or metal deck with concrete fill and are stiff relative to the frames. Where the exterior of the structure is concealed, walls consist of metal panel curtain walls, glazing, brick masonry, or precast concrete panels. Where the interior of the structure finished, frames are concealed by ceilings, partition walls, and architectural column furring. The foundation system may consist of a variety of elements [4].

In Tier-1, there are two kinds of checklists which consist of structural and nonstructural. The structural checklist is basic,

supplement and Foundation. On the other hand, Nonstructural consist of basic and supplement. The flowchart for Tier-1 can be seen in Fig. 1.





Fig -1: Flowchart of rapid evaluation procedure

In Tier-1, there are two kinds of checklist which consist of structural and nonstructural. The structural checklist is basic, supplement and Foundation. On the other hand, Nonstructural consist of basic and supplement. Table 2 and Table 5 show checklist evaluation procedure.

## 3. CASE STUDY


A Case study conforms to common building type S1 steel moment frame in ASCE 41-13 benchmark. Structure model is steel special moment frame which consists of 6th stories. It has three bays in x-direction with length 5 m per each and three bays in y-direction with length 6 m per each. Plan and perspective view can be seen in Figure 2.

The model was analyzed for gravity and seismic load using Indonesian code refer to SNI 1727:2013 and SNI 1726:2012 respectively [5,6]. The seismic hazard caused by ground shaking shall be based on the location of the building concerning causative faults, the regional and site-specific geologic and geotechnical characteristics, and the specified Seismic Hazard Levels.



**Fig-2:** The 6<sup>th</sup> stories structure model

The structure is located in Padang city of Indonesia which has a high level of seismicity and site class stiff soil. Seismic design categories base on design spectral response is D category [6]. Figure 3 shows a map of the risk-adjusted maximum considered earthquake in Indonesia.



**Fig -3:**  $S_s$  Risk-Adjusted Maximum Considered Earthquake ground motion parameter in Indonesia [6].

The design generated according to specification for structural steel buildings in Indonesia refers to SNI 1729:2015 [7,8,9][6]. The target of structural performance is collapse prevention (CP) and nonstructural is similar to structural performance level. Summarize of design section can be seen in Table 1.

**Table -1:** Summarize of section property

| No | Description             | WF Section    | Fy (Mpa) | Fu (Mpa) | Material Standard |
|----|-------------------------|---------------|----------|----------|-------------------|
| 1  | Column 1st -3rd Stories | 400.400.13.21 | 345      | 450      | A 992             |
| 2  | Column 4th -6th Stories | 300.300.10.15 | 345      | 450      | A 992             |
| 3  | Beam                    | 400.200.8.13  | 345      | 450      | A 992             |

#### 4. RAPID EVALUATION METHOD

Rapid evaluation method refers to the checklist in tier 1 in ASCE 41-13 guideline. Requirement checklist for high seismicity level and immediate occupancy performance level consist of 3 part evaluation. Part 1 is basic checklist

procedure concerning the configuration of building and foundation. In this part also evaluated the location of building concerning geologic site hazard system as shown in Table 2. The basic checklist applies to all building type and all performance target level. Part 2 is structural checklist procedure which distinguishes for all building type. Immediate occupancy performance has more detail checklist compared to life safety as shown in Table 5. The other is non structural checklist. Nonstructural objective is architectural, mechanical and electrical components that are permanently installed in a building system.

Each of the evaluation statements in this checklist shall be marked Compliant (C), Noncompliant (NC), Unknown (U), or Not Applicable (N/A). Compliant statements identify issues that are acceptable according to the description criteria, whereas noncompliant and unknown statements identify issues that require further investigation. Not applicable is used to indicate when description does not apply to a particular case or because the description is not available.

**Table -2:** Basic configuration checklist

| No                                 | Description checklist            | Result | Remark                                                       |
|------------------------------------|----------------------------------|--------|--------------------------------------------------------------|
| <b>A. Building System</b>          |                                  |        |                                                              |
| <b>General</b>                     |                                  |        |                                                              |
| 1                                  | Load Path                        | C      | There is no discontinuity of element to resist seismic force |
| 2                                  | Adjacent Buildings               | C      | There is no building at distance 2 meters                    |
| 3                                  | Mezzanines                       | C      | No mezzanine floor                                           |
| <b>Building Configuration</b>      |                                  |        |                                                              |
| 4                                  | Weak Story                       | NC     | In story 3 and 4, the sum strength is 60% (Less than 80%)    |
| 5                                  | Soft Story                       | NC     | In story 3 and 4, the sum stiffness is 30% (Less than 80%)   |
| 6                                  | Vertical Irregularities          | C      | No shear wall and brace frame                                |
| 7                                  | Geometry                         | C      | No Setback                                                   |
| 8                                  | Mass                             | C      | No Heavy floor                                               |
| 9                                  | Torsion                          | C      | No Torsion                                                   |
| <b>B. Geologic Site Hazards</b>    |                                  |        |                                                              |
| 10                                 | Liquefaction                     | C      | No potential liquefaction due to soft soil                   |
| 11                                 | Slope Failure                    | C      | No slope close to building                                   |
| 12                                 | Surface Fault Rupture            | C      | No potential for large fissures and differential movement    |
| <b>C. Foundation Configuration</b> |                                  |        |                                                              |
| 13                                 | Overturning                      | C      | Deep foundation, the ratio less than 0.6 Sa                  |
| 14                                 | Ties Between Foundation Elements | C      | Adequates tie beams                                          |

Table 2 shows the result evaluation of part 1 procedure. There were two non-compliant items weak story and soft

story. The first is dimension of the steel section in story 4 (WF 300.300.10.15) smaller than story 3 (WF 400.400.13.21) and the second is the differences shear strength 58% (Table 3). If the shear strength less than 80%, it has potential to be weak story failure.

**Table -3: Weak story evaluation**

| Story no  | Column section   | Relative Shear strength | Ratio adjacent story | Remarks |
|-----------|------------------|-------------------------|----------------------|---------|
| Story - 6 | WF 300.300.10.15 | 2700                    | -                    |         |
|           |                  |                         | 100%                 |         |
| Story - 5 | WF 300.300.10.15 | 2700                    | 100%                 |         |
|           |                  |                         | 100%                 |         |
| Story - 4 | WF 300.300.10.15 | 2700                    | 100%                 |         |
|           |                  |                         | 58%                  | < 80 %  |
| Story - 3 | WF 400.400.13.21 | 4654                    | 172%                 |         |
|           |                  |                         | 100%                 |         |
| Story - 2 | WF 400.400.13.21 | 4654                    | 100%                 |         |
|           |                  |                         | 100%                 |         |
| Story - 1 | WF 400.400.13.21 | 4654                    | 100%                 |         |
|           |                  |                         | -                    |         |

The stiffness of the seismic resisting system in any story is not less than 70% of stiffness in an adjacent story above or less than 80% of the average seismic force-resisting system stiffness of the three stories above [10, 11]. However story three and four have the differences stiffness is 30% (Table 4).

**Table -4: Soft story evaluation**

| Story No  | Column section   | Relative Stiffness | Ratio adjacent story | Remarks |
|-----------|------------------|--------------------|----------------------|---------|
| Story - 6 | WF 300.300.10.15 | 39,800             | -                    |         |
|           |                  |                    | 100%                 |         |
| Story - 5 | WF 300.300.10.15 | 39,800             | 100%                 |         |
|           |                  |                    | 100%                 |         |
| Story - 4 | WF 300.300.10.15 | 39,800             | 100%                 |         |
|           |                  |                    | 30%                  | < 70 %  |
| Story - 3 | WF 400.400.13.21 | 130,800            | 329%                 |         |
|           |                  |                    | 100%                 |         |
| Story - 2 | WF 400.400.13.21 | 130,800            | 100%                 |         |
|           |                  |                    | 120%                 |         |
| Story - 1 | WF 400.400.13.21 | 109,000            | 83%                  |         |
|           |                  |                    |                      |         |

Further evaluation for structural checklist describes in Table 5. There were some deficiencies found in structural evaluation. Lack of column flexural stress due to the strong column and weak beam not compliant. Similar problem to the previous finding, it was because of section geometry

smaller at store 4 to 6. The selected dimension of steel section must be considered to the limitation of compactness section. Infill walls placed in moment frame designed not to resist seismic load subjected to damage due to no isolation. Detailing beam column joint and panel zone also needs to be focused on the steel structure.

**Table -5: Structural checklist for steel moment with immediate occupancy performance (ASCE 41-13)**

| No                                       | Description checklist           | Check | Remark                                                                                                 |
|------------------------------------------|---------------------------------|-------|--------------------------------------------------------------------------------------------------------|
| <b>A. Seismic-Force-Resisting System</b> |                                 |       |                                                                                                        |
| 1                                        | Drift check                     | C     | Story drift ratio < 0.025                                                                              |
| 2                                        | Column axial stress check       | C     | Columns < 0.1 Fy (gravity only), Alternatively, columns, equation (4-12) < 0.3 Fy (overturning alone)  |
| 3                                        | Flexural stress check           | NC    | No strong column-weak beam in story 3                                                                  |
| 4                                        | Redundancy                      | C     | Redundant frame (3 bays)                                                                               |
| 5                                        | Interfering walls               | NC    | No isolation for wall (Wall subjected to damage)                                                       |
| 6                                        | Transfer to steel fra           | C     | Floor have adequate connection with frame structure (welded and shear studs)                           |
| 7                                        | Steel columns                   | C     | the foundation and anchorage system is able to develop the least of the tensile capacity of the column |
| 8                                        | Moment-resisting connection     | NC    | Considering as no compliant for further analysis                                                       |
| 9                                        | Panel zones                     | NC    | Considering as no compliant for further analysis (there is no treatment for PZ)                        |
| 10                                       | Column splices                  | C     | No column splice                                                                                       |
| 11                                       | Strong column - weak beam       | NC    | Not satisfy > 50% SCWB check for each story                                                            |
| 12                                       | Compact members                 | NC    | Non compact element                                                                                    |
| 13                                       | Beam penetrations               | C     | No web opening in beam frame                                                                           |
| 14                                       | Girder flange continuity plates | C     | Continuity plates installed                                                                            |
| 15                                       | Out-of-plane bracing            | NC    | No out of plane bracing                                                                                |
| 16                                       | Bottom flange bracing           | C     | Bottom flange bracing installed                                                                        |
| <b>B. Diaphragms</b>                     |                                 |       |                                                                                                        |
| 17                                       | Plan irregularities             | C     | Regularities                                                                                           |
| 18                                       | Diaphragm reinforcement         | C     | No diaphragm opening                                                                                   |
| 19                                       | Openings at frames              | C     | No diaphragm opening                                                                                   |
| <b>C. Foundation system</b>              |                                 |       |                                                                                                        |
| 20                                       | Deep foundations                | C     | Adequate piles and pier                                                                                |
| 21                                       | Sloping sites                   | NA    | No sloping site                                                                                        |

The next procedure is evaluated nonstructural part. Nonstructural Component such as an architectural, mechanical, or electrical component of a building that is permanently installed a building system is considered in compliant condition.

## 5. CONCLUSIONS

A rapid evaluation method has been conducted to 6 stories building steel moment frame. The evaluation refers to ASCE 41-13 Seismic Evaluation and Retrofit of Existing Building. There are three parts of the procedure has been done, basic checklist concerning structure geometry and configuration, a structural checklist with focusing lateral force resisting element and nonstructural checklist.

Weak story and soft story able to detect rapidly in the basic checklist. Furthermore, For the structural checklist, deficiencies in column flexural stress due to "strong column and weak beam" not compliant. Infill walls placed in moment frame designed not to resist the seismic load subjected to damage due to no isolation. Detailing beam column joint and panel zone stiffness also needs to consider the steel structure. The result of this rapid evaluation recommends that this building requires further evaluation.

## ACKNOWLEDGEMENT

The first author would like to acknowledge financial support from the Indonesian Endowment Fund for Education (LPDP), Ministry of Finance; and the Directorate General of Higher Education (DIKTI), Ministry of Research, Technology and Higher Education, Republic of Indonesia.

## REFERENCES

- [1] Kurniawandy, A., et al., "Structural building screening and evaluation", AIP Conference Proceeding 1892, Ignite Conference, Penang, 2017.
- [2] USGS National Earthquake Information Center, Regional Information, [accessed 2018 January 25]. <https://earthquake.usgs.gov/earthquakes/eventpage/u-s2000cmwz#region-info>.
- [3] FEMA 310, "Handbook for the Seismic Evaluation of Buildings", Federal Emergency Management Agency, Washington DC, United States of America, 1998.
- [4] ASCE/SEI 41-13, "Seismic Evaluation and Retrofit of Existing Building", American Society of Civil Engineers, Virginia, United States of America, 2014.
- [5] Indonesian Code, SNI 1727:2013, "Beban minimum untuk perancangan bangunan gedung dan struktur lain", Badan Standarisasi Nasional, Jakarta, 2013.
- [6] Indonesian Code, SNI 1726:2012, "Tata Cara Perencanaan Ketahanan Gempa Untuk Struktur Bangunan Gedung dan Non Gedung", Badan Standarisasi Nasional, Jakarta, 2012.
- [7] Indonesian Code, SNI 1729:2015, "Spesifikasi untuk bangunan gedung baja struktural", Badan Standarisasi Nasional, Jakarta, 2015.
- [8] Wiliam T. Segui, "Steel Design", Fifth Edition, Cengage Learning, United States of America, 2013.
- [9] Bruneau, M., Uang, C., Sabelli, R., "Ductile Design of Steel Structures", Second Editions, McGraw Hill, United States of America, 2011.
- [10] ANSI/AISC 341-10, "Seismic Provisions for Structural Steel Buildings", American Institute of Steel Construction, United States of America, 2010.
- [11] ANSI/AISC 360-10, "Specification for Structural Steel Buildings", American Institute of Steel Construction, United States of America, 2010.